

# Graymont Pilot Peak Truck Loading Procedure

- Truck drivers must remain in cab while being loaded, maintain open communication with scale hand
- Self loading drivers (hydrate) (LKD) use best practice, all PPE must be worn, wheels must be chocked
- Loading of open top trailers, maintain open communication with loader, driver must remain in cab until loaded, move truck only when instructed to do so
- All drivers loading at Pilot Peak must maintain open communication with scale hand or loader operator, drivers must always stay in their cab when being loaded, except self loading drivers (hydrate) (LKD)
- Graymont haul truck drivers must remain in cab while being loaded, haul trucks without a driver in cab **MUST NOT** be loaded